



TECHNICAL FIELD BULLETIN



Date August 2004
Subject D8 Motor Speed
Issue By NKL Cash Handling - a member of FKI Security Group
Issue To FKI Sales, Field Service & Technical Support
Document 40801

PRODUCTS AFFECTED

D8C, D8R and D8X.

OVERVIEW

Bulletins 40305 and 40505 describe detailed updates regarding vend motors and supporting software. This bulletin is to inform you any motor marked 42.5 RPM to 46.5 RPM is acceptable in any D8 (in accordance with bulletins 40305 and 40505 which refer only to 46.5 RPM).

ACTION REQUIRED

This bulletin is provided for information purposes only and is supplemental to bulletins 40305 and 40505. Anywhere in those bulletins where a speed of 46.5 RPM is indicated, 42.5 RPM is also acceptable.

ADDITIONAL INFORMATION

This bulletin should clear up any confusion caused by the 42.5 RPM markings found on some vend motors.