



# TECHNICAL FIELD BULLETIN



Date August 2004  
Subject AuditLok XLV Lock Boards  
Issue By NKL Cash Handling - a member of FKI Security Group  
Issue To FKI Sales, Field Service & Technical Support  
Document 40803

## PRODUCTS AFFECTED

All products using AuditLok XLV electronics.

## OVERVIEW

The software code for the lock board used in AuditLok XLV products has been updated to Version .49. This revision resolves an issue with setting up timelock settings stored on the lock board, specifically affecting Tuesday and Saturday parameters.

## ACTION REQUIRED

Replace lock boards with Version .49 if timelocks do not function properly, specifically on Tuesday and/or Saturday. If the timelocks are not used and/or there are no problems found with the function of timelocks, this update is not necessary. If this update is determined to be necessary, replace all lock boards in the system where timelocks are used.

## ADDITIONAL INFORMATION

Contact NKL Technical Service (1-800-452-4655) to determine if this update is needed for each instance where you suspect timelock problems.