



TECHNICAL FIELD BULLETIN



Date September 2004
Subject AuditLok XLV Software Update
Issue By NKL Cash Handling - a member of FKI Security Group
Issue To FKI Sales, Technical Support, Field Service & Service Partner Network
Document 40902

PRODUCTS AFFECTED

Safes with AuditLok XLV electronics. First serial number with Version 3.37 from production: SP2004037064.

OVERVIEW

This revision of AuditLok XLV (Version 3.37) supercedes Version 3.35 and all previous versions. The software change corrects issues from previous releases. Relative to Version 3.35: improved bill count accuracy and corrected autodelete feature when using Biometrics (fingerprint) technology. There are no new features with this release. It is not necessary to upgrade existing products unless specifically directed by NKL Technical Support.

ACTION REQUIRED

Perform updates (load software or replace “can”) only at the direction of NKL Technical Service.

1. To load software (S/N SP2004030002 or above only): Obtain update software, display and connector kit, and instructions from NKL Technical Support (800-452-4655). Follow the directions supplied by NKL to perform the software update.
2. Replace the CPU “can” in accordance with Service Manual instructions.

ADDITIONAL INFORMATION

Refer to the Procedures for Updating Software and the Autobank Service Manual for additional printed instructions. For more information call NKL Technical Service at 1-800-452-4655.

NKL Cash Handling is a member of the FKI Security Group
101 Security Parkway - New Albany IN 47150
1-800-528-9900 - www.nklcashhandling.com

